



FIA World Endurance Championship

TOTALENERGIES 6 Hours of SPA

From: the Race Director

Communication N° 02/2026

To: all Entrants in the Championship

INFORMATION

Due to unknown factors the technical department has identified that there is a time latency, when Race Control deploy FCY or VSC in full automatic mode.

To mitigate the above and safeguard drivers' safety and sporting equity the following will be applied.

- 1. The hour of start of a FCY or VSC will be typed manually on the timing monitors.*
- 2. The indication of "prepare for FCY at" may be earlier thus, pit entry closed preceding a FCY may be slightly longer.*
- 3. The countdown will be done the old way with a human being doing it instead of the automated voice.*
- 4. The onboard marshaling display will not have the visual decreasing countdown.*
- 5. The tolerance to be at 80kph will be increased from 3 seconds to 5 seconds.*
- 6. The countdown to remove the FCY will also be done by a human voice, and the extinction of the FCY info on the onboard will also be done manually.*

Eduardo Freitas
FIA Race Director

Date: 09/05/2026

Time: 09.18

Document N°: